



CULVERT REPAIR AND MAINTENANCE Smarter – Faster and more Efficient!

Solum, a private company supplying a wide range of environmental services was asked to repair a culvert gate for the municipality of Frederikssund.

They decided to use a range of our NoFloods Barriers to dam up the stream and secure a safe and dry work environment.

This helped them to optimize the process of repair and maintenance.

Approximately 20m of NoFloods Barriers and 10m of NoFloods FlexWall was easily deployed in damming up the stream.

Water level was maintained by pumps to avoid overflow.

Start


















Finish









































Environment Solutions Science and Technology ApS Universitetsparken 7 – 4000 Roskilde, Denmark

Environment Solutions Inc. 228 Park Avenue S, #300, New York, NY 10003, USA

www.nofloods.com info@nofloods.com